



Product Information

www.miller-stephenson.com

MS-136W/145W Water-based PTFE Release Agent

Description:

Miller-Stephenson's PTFE release agent is a water based formulation which utilizes sub 1.0 micron PTFE (polytetrafluoroethylene) particles to impart superior lubricity, surface adhesion and durability, and outstanding mold release efficiency. The outstanding lubricity and extremely low coefficient of friction of this water based PTFE has been optimized for hot mold application (>190 F / 88 C). The formulation has been further enhanced with proprietary surface activation chemistry to increase adhesion of the PTFE to the molding surface. The result is a water-based release agent that is very cost-effective by maximizing releases per application and decreasing down-time. Benefits of this product include:

- Water-based formulation; Hot mold optimized
- Enhanced surface adhesion; Maximized durability
- Excellent release of all polymer types
- Non-flammable; No VOC; No GWP
- Non-migrating

Release Agent Applications

MS-145W can be used to release the following materials with virtually no transfer of the release agent:

- Plastics
- Resins
- Acrylics
- Urethanes
- Nylons
- Rubbers
- Phenolics
- Polycarbonates
- Polystyrene
- Elastomers

Physical Properties:

Primary Polymer:.....Fluoropolymer
Appearance:.....Light Yellow Emulsion
Odor:.....None
Specific Gravity:.....1.0 g/mL @ 25°C
Flash Point:.....None

Recommended Application Procedure:

1. Clean mold surface thoroughly. Mechanical cleaning such as, bead media blasting or steel wool, followed by chemical cleaning, provides the best surface for application of MS-136W/145W. Removal of all previous mold release agent is critical.
2. Mix product thoroughly prior and continuously during use. If spraying, use spray equipment which provides a fine mist and ensure product is applied "wet". Proper air pressure and spray distance is critical for correct application of this product. Apply to mold surface which is above 90°C.
3. Allow water to vaporize completely before molding any parts. Failure to wait will result in drastically reduced product performance.

Reapplication:

1. When release becomes hesitant, reapply one coat of MS-136W / 145W in the same manner as described above.

Fused Coatings Procedure

1. After applying the release agent, heat the surface to 581°F - 600°F. Measure the surface temperature directly with a thermocouple.
2. A change in coating appearance from an opaque white to a darker, translucent will occur. Maintain the temperature of the coated surface for 5 to 10 minutes.
3. If a white residue is left on the metal surface, buff with a soft cloth. When the coating is properly fused, it is extremely durable.

Safety data sheets (SDSs) are available upon request.

1462-3M

The recommendation made here with and the information set forth with respect to the performance or use of our products are believed, but not warranted to be accurate. The products discussed are sold without warranty, as to fitness or performance, express or implied and upon condition that purchasers shall make their own test to determine suitability of such products for their particular purposes. Likewise, statements concerning the possible uses of our products are not intended as recommendations to use our products in the infringement of any patent.

For technical information call 800.992.2424 or 203.743.4447
For product sales: CT 800.442.3424, CA 800.771.8161, IL 800.447.4866, Canada 800.307.2199
www.miller-stephenson.com

Miller-Stephenson logo are trademarks of Miller-Stephenson Chemical Company Inc